NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION Quarterly Defect Report Required per CFR Part 573.6

Report Date: April 5, 2004 Calendar Quarter: 3

Safety Recall Quarterly Report from: September 10, 2003 through April 1, 2004

Manufacturer: Fleetwood Enterprises, Inc.

Report Author: Robert E. Wozniak Phone: 909-351-3814

Recall Subject: 2002, 2003 & Early 2004 Revolution & Early 2004 American Tradition &

American Eagle - Auxiliary Battery Disconnect

NHTSA Safety Recall Campaign Number: 03V-304

Also, for completeness, if your company has assigned a code number to this campaign, provide your code: 30815

(a) The date notification to purchasers began:

1st mailing: September 10, 2003 2nd mailing: February 4, 2004

- (b) The date the 3rd notification mailing to purchasers was completed:
- 3. The total number of items involved: 1273

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer / importer).

Number of items returned from inventory or remedied prior to sale: 5
Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers. Do not include this number in 4 (a) or 4 (b).

- 4. (a) Total number inspected and remedied: 574

 Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).
 - (b) Total number inspected and NOT REQUIRING REMEDY: 48 Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.
- Items determined to be UNREACHABLE: 3

Total number exported:

Total number stolen:

Total number scrapped:

Total number unable to identify:

Total number otherwise unreachable:

3